




UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137



MAY 15 1981

License No. 24-02564-02

Midwest Research Institute
ATTN: Edward J. Ogilvie II
Radiation Safety Officer
425 Volker Boulevard
Kansas City, Missouri 64110

Gentlemen:

This refers to the routine safety inspection conducted by Mr. R. E. Burgin and Dr. W. J. Adam of this office on April 29, 1981, of activities authorized by NRC Byproduct Material License No. 24-02564-02 and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

This inspection also included a review of actions taken to correct the items of noncompliance identified during our May 1977, inspection. We have no further questions in regard to these matters.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in enclosed Appendix A. A written response, submitted under oath or affirmation, is required.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. G. Wiedeman, Acting Chief
Materials Radiation Protection
Section 1

Enclosure: Appendix A,
Notice of Violation

cc w/encl:
Central Files
Reproduction Unit NRC 20b
PDR
NSIC

8106120 385