



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

Report Nos. 50-348/81-08 and 50-364/81-11

Licensee: Alabama Power Company
600 North 18th Street
Birmingham, AL 35202

Facility Name: Farley

Docket Nos. 50-348 and 50-364

License Nos. NPF-2 and NPF-8

Inspection at Farley Nuclear Plant near Ashford, Alabama

Inspector

J. A. Peebles

J. A. Peebles

5/5/81
Date Signed

Approved by

J. C. Bryant

J. C. Bryant

5/5/81
Date Signed

SUMMARY

Inspection on April 14 - 17, 1981

Areas Inspected

This routine, announced inspection involved 24 inspector-hours on site in the areas of operator requalification training and training to the TMI Task Action Plan commitments.

Results

Of the two areas inspected, no violations or deviations were identified in either area.

8106150606

DETAILS

1. Persons Contacted

Licensee Employees

- *W. G. Hairston, Plant Manager
- *W. C. Carr, Supervisor of SAER
- *Lee S. Williams, Training Superintendent
- *L. L. Bailey, QA Engineer
- *J. W. Kale, SAER Engineer

Other licensee employees contacted included 6 operators and 5 office personnel.

NRC Resident Inspector

- *W. H. Bradford

*Attended exit interview

2. Exit Interview

The inspection scope and findings were summarized on April 17, with those persons indicated in paragraph 1 above.

3. Licensee Action on Previous Inspection Findings

Not inspected.

4. Unresolved Items

Unresolved items were not identified during this inspection.

5. Requalification Training

The inspector attended two of the licensee's operator requalification lecture series and verified that lesson plan objectives were met and that training was in accordance with the approved operator requalification program schedule and objectives. The inspector reviewed training records to verify that all of the on site licensed personnel were current with the requalification requirements and that the course tests had been satisfactorily completed. The inspector verified by direct questioning of six licensed personnel that training had been conducted and that course objectives had been met.

The inspector found the licensee's training program to be beneficial for the personnel and the regulatory requirements.

6. TMI Action Items

The inspector verified that licensee commitments were being met in having a functioning program for feedback of operating experience to the plant staff, that training had been conducted for all operations personnel in all start-up tests to be conducted, and that the operator training program included the principles of heat transfer and fluid mechanics. The inspector found these items to be complete.