FORM NRC-591

U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

General Motors Corporation Manufacturing Development General Motors Technical Center 12 Mile & Mound Road - Warren, Mich. 48090		Region 111 799 Roosevelt Rd. Glen Ellyn, II 60137	
30-4914	21-12535-01		6-3-81
inspection Findings The inspection was an examination of Commission's rules and regulations and sentative records, interviews with personant control of the	of the activities conducted under your did the conditions of your license. The	or license as they relate to inspection consisted of sel tor. The findings as a result	radiation safety and to compliance with the lective examinations of procedures and repre-
	pliance related to records, signs, a		
			TION AREA. 10 CFR 20.203(b) or 34.43
	ot properly posted to indicate the		
C. Rooms or areas were no 10 CFR 20.203(d)	ot properly posted to indicate the	presence of an AIRBO	RNE RADIOACTIVITY AREA.
D. Rooms or areas were no	ot properly posted to indicate the	presence of RADIOAC	CTIVE MATERIAL. 10 CFR 20.203(e)
E. Containers were not pro 10 CFR 20.203(f) (1) of	operly labeled to indicate the pre or (f) (2)	sence of RADIOACTIV	E MATERIAL.
F. A current copy of 10 C made available, 10 CFR	FR 20, a copy of the license, or a 20.206(b)	a copy of the operating	procedures was not properly posted or
☐ G. Form NRC-3 was not p	roperly posted. 10 CFR 20.206(c	:)	
☐ H. Records of the radiation	n exposure of individuals were no	ot properly maintained.	10 CFR 20.401(a) or 34.33(b)
☐ I. Records of surveys or d	isposals were not properly maint	ained. 10 CFR 20.401(b) or 34.43(d)
J. Records of receipt, tran 10 CFR 30.51, 40.61 o	isfer, disposal, export or inventor r 70.51	y of licensed material w	vere not properly maintained.
K. Records of leak tests we	ere not maintained as prescribed	in your license, or 10 C	FR 34.25(c)
☐ L. Records of inventories	were not maintained. 10 CFR 34	.26	1607
☐ M. Utilization logs were no	ot maintained. 10 CFR 34.27		1607
☐ N. Records of radiation su	rvey instrument calibration were	not maintained. 10 CFI	R 34.24 1/0
O. Records of teletherapy	electrical interlock tests were not	t maintained as prescrib	ed in your license.
P. Other		Bracker 1	
	Evely	R Mil	sun ton
 The NRC Inspector has expl noncompliance will be corre 	lained and I understand the ite cted within the next 30 days.	ms of noncompliance	listed above. The items of
(Date)		(Licensee Representat	ine - Title or Position)

ORIGINAL TO LICENSEE