Southern California Edison Company

P. O. BOX 800 2244 WALNUT GROVE AVENUE ROSEMEAD CALIFORNIA 91770 June 9, 1981

J. G. HAYNES MANAGER OF NUCLEAR OPERATIONS

> U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region V 1990 North California Boulevard Suite 202, Walnut Creek Plaza Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Dear Sir:

Subject: Docket No. 50-206 IE Bulletin 80-21 Valve Yokes Supplied by Malcolm Foundary Co., Inc. San Onofre Nuclear Generating Station Unit 1

Reference: Letter, J. G. Haynes (SCE) to R. H. Engelken, (NRC), Valve Yokes Supplied by Malcolm Foundary Co., Inc., December 10, 1980

In the referenced letter, SCE committed to submit a complete response to IE Bulletin 80-21 prior to return to power from this outage.

Suppliers of active safety-related valves for San Onofre Unit 1 have been contacted. It has been determined that only Anchor Darling has ever used castings made by Malcolm Foundary. Anchor Darling has determined that none of the valves supplied by them for San Onofre Unit 1 had parts cast by Malcolm Foundary.

If you have any questions, please let me know.

Sincerely, VGr Haynes

cc: Office of Inspection and Enforcement Division of Reactor Construction Inspection Washington, D.C. 20555

> L. Miller NRC Resident Inspector, San Onofre Unit 1

IE11 51/0

,8106160222

_

.....

TELEPHONE

(213) 572-1742