



Commonwealth Edison
 Zion Generating Station
 Shiloh Blvd. & Lake Michigan
 Zion, Illinois 60099
 Telephone 312/746-2084

DMB/LER

June 5, 1981

Mr. James G. Keppler
 Regional Director
 Office of Inspection and Enforcement
 Region III
 U.S. Nuclear Regulatory Commission
 Glen Ellyn, Illinois 60137



Reference: Zion Generating Station
 Docket No. 50-295/DPR-39
 Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/81-21 for Zion Generating Station. This occurrence was reported to Region III, Directorate of Regulatory Operations by telephone on 5/27/81 and by telegram on 5/27/81.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.a(2) which states that operation of the unit or affected systems when any parameter or operation subject to a limiting condition is less conservative than the least conservative aspect of the limiting condition for operation established in the technical specifications require a 14 day written report.

Very truly yours,

K. L. Graesser

K. L. Graesser
 Superintendent
 Zion Station

cc: J. Kohler/J. Waters

Enclosure: Reportable Occurrence Report No. 50-295/81-21

IE22
 S/1

8106160528

5

JUN 8 1981