

## 6.0 ADMINISTRATIVE CONTROLS

### 6.1 RESPONSIBILITY

- 6.1.1 The General Manager shall be responsible for overall facility operation and shall delegate in writing the succession to this responsibility during his absence.

### 6.2 ORGANIZATION

#### OFFSITE

- 6.2.1 The offsite organization for facility management and technical support shall be as shown on Figure 6.2-1.

#### FACILITY STAFF

- 6.2.2 The Facility organization shall be as shown on Figures 6.2-2A, B, C, and D. Each on duty shift shall be composed of at least the minimum shift crew composition shown in Table 6.2-1.

### 6.3 FACILITY STAFF QUALIFICATIONS

- 6.3.1 Each member of the facility staff shall meet or exceed the minimum qualifications of ANSI N18.1-1971 for comparable position, except for the Health Physics Supervisor who shall meet or exceed the qualifications of Regulatory Guide 1.8, September 1975.

### 6.4 TRAINING

- 6.4.1 A retraining and replacement training program for the facility staff shall be maintained and shall meet or exceed the requirements and recommendations of Section 5.5 of ANSI N18.1-1971 and Appendix "A" of 10 CFR Part 55.
- 6.4.2 A training program for fire protection training shall be maintained and shall meet or exceed the requirements of Section 27 of the NFPA Code-1975 with the exception of frequency of training which shall be held at least quarterly.

### 6.5 REVIEW AND AUDIT

#### 6.5.1 Plant Safety Committee (PSC) Function

- 6.5.1.1 The Plant Safety Committee shall function to advise the General Manager on all matters related to nuclear safety.

#### COMPOSITION

- 6.5.1.2 The Plant Safety Committee shall be composed of the:

Amendment No.