

APPENDIX A

NOTICE OF VIOLATION

Somerville Hospital
Somerville, Massachusetts 02145

Docket No.: 30-2176
License No.: 20-14009-01

As a result of the inspection conducted on April 14, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:


- A. 10 CFR 35.14(e) requires that sealed calibration or reference sources possessed pursuant to 10 CFR 35.14(d) be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to this requirement, as of the day of the inspection, April 14, 1981, you have failed to leak test your 217 microcurie sealed cesium-137 reference source which you received in 1975, an interval of more than six months.

This is a Severity Level V Violation. (Supplement VII)

Pursuant to the provisions of 10 CFR 2.201, Somerville Hospital is hereby required to submit to this office within twenty-five days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations, and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

Dated 1 JUN 1981


John D. Kinneman, Chief
Materials Radiological Protection
Section