

TULSA GAMMA RAY, INC.

1127 SOUTH LEWIS
TULSA, OKLAHOMA 74104
585-3228

April 22, 1981

JAMES C. MOSS
PRESIDENT

Nuclear Regulatory Commission
Mr. Glen D. Brown
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Re: License No. 35-17178-01
Notice of Violation
Docket #30-12319

Dear Mr. Brown:

Reference your letter of 7 April 1981 concerning the Routine Safety Inspection conducted by Mr. Jack E. Whitten.

Immediate corrective action has been taken to correct the deficiencies noted in Mr. Whitten's report as of 17 April 1981. Corrections are as indicated:


- (1) All personnel have been briefed as to the correct survey to be accomplished of radiographic exposure devices, IAW 10 CFR34.43(b). A constant check of personnel will be conducted to insure they are conducting this survey properly.
- (2) All packages received containing radioactive material are being surveyed at time of receipt. Increased emphasis will be placed on this survey and proper recording of these surveys will be completed.

All personnel have been briefed on this deficiency and instructed how these surveys are to be conducted and recorded, IAW 10 CFR20.205(c)(1).

I certify that all information contained in this letter is true and correct to the best of my knowledge and belief.

Sincerely yours,

Subscribed and Sworn to before me
this _____ day of _____, 19____


James C. Moss, President
Tulsa Gamma Ray, Inc.

Notary

JCM . gs

My Commission Expires March 12, 1984

8106190337