



LER #: 50-366/1981-050  
LICENSEE: Georgia Power Company  
FACILITY NAME: Edwin I. Hatch  
DOCKET #: 50-366

Narrative Report  
for LER 50-366/1981-050

During a Q.A. Audit it was discovered that a mathematical error had been made in keeping the run times on SBT Filter Train "B" (2T46-D001D) that resulted in exceeding the sampling frequency requirements of Tech. Specs. 4.6.6.1.1.c.

After discovery of the mistake the required sample was taken as soon as possible.

A memo was sent to Operations personnel involved in keeping equipment run times reminding them of the importance of keeping correct records.