



SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

June 22, 1981

R H ENGELKEN, DIRECTOR  
REGION V OFFICE OF INSPECTION & ENFORCEMENT  
U S NUCLEAR REGULATORY COMMISSION  
1990 N CALIFORNIA BLVD  
WALNUT CREEK PLAZA SUITE 202  
WALNUT CREEK CA 94596



OPERATING LICENSE DPR-54  
DOCKET NO. 50-312  
REPORTABLE OCCURRENCE 81-31

In accordance with Technical Specifications, Section 6.9.4.2.b and 3.14.6.1, the Sacramento Municipal Utility District hereby submits a thirty-day report of Reportable Occurrence 81-31.

On May 20, performance of a routine surveillance procedure revealed a number of Cable Tray Fire Barrier failures. Two subsequent inspections under the same surveillance procedure, on June 1 and June 9, revealed additional fire barrier failures. A firewatch was established at each affected fire barrier, and work requests were written to repair each.

To prevent fire barrier failures from going undetected during on-going plant modifications, the Supervising Civil Engineer is establishing a log to keep track of all fire barriers as they are compromised. This will provide for immediate notification of the Control Room and of the Safety Technician, so that firewatches can be established.

There were no transients or power reductions associated with this event.

*John J. Mattimoe*

John J. Mattimoe  
Acting General Manager

cc: I&E Washington (30)  
MIPC (3)  
EPRI-NSAC

8106300029

S