


JUN 18 1981



License No. 21-10983-01

John V. Dimanin, D.O.
ATTN: Dr. Dimanin
14853 Michigan Avenue
Dearborn, MI 48126

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. R. Mullauer of this office on June 1, 1981, of activities authorized by NRC Byproduct Material License No. 21-10983-01 and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in enclosed Appendix A. A written response, submitted under oath or affirmation, is required.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2

Enclosure: Appendix A,
Notice of Violation

cc w/encl:
DMB/Document Control Desk (RIDS)

IE07
s
1/1

RIII
Mullauer/jp
6/17/81

RIII
DJS
Sreniawski
6/18/81

8106300475