



PDR

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAY 28 1981

Raymond Sneider, D.O.
Plumbrook Medical Center
39880 Van Dyke
Sterling Heights, MI 48078

License No. 21-17099-01

Gentlemen:

This refers to the routine safety inspection conducted by Ms. E. Matson and Mr. J. R. Mullauer of this office on May 12, 1981, of activities authorized by NRC Byproduct Material License No. 21-17099-01 and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in enclosed Appendix A. A written response, submitted under oath or affirmation, is required.

In addition to the above areas, the inspector examined actions described in your letters dated May 3, and June 21, 1978, regarding the apparent item of noncompliance found during our March 13, 1978, inspection. We have no further questions regarding this matter.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2

Enclosure: Appendix A,
Notice of Violation

cc w/encl:
Central Files
Reproduction Unit NRC 20b
PDR
NSIC



8106300541