

Appendix A

NOTICE OF VIOLATION

Outer Drive Hospital

License No. 21-13389-01

As a result of the inspection conducted on June 5, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violations were identified:

1. Condition No. 16 of your license requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in the referenced application and letter.

The referenced application dated August 14, 1979, states in Item 7, the Medical Isotope Committee will meet in accordance with Regulatory Guide 10.8, dated November 1, 1977, Appendix B. Appendix B requires the Committee to meet no less than quarterly.

Contrary to the above, the Medical Isotope Committee did not meet from October 13, 1978, to July 13, 1979; from July 13, 1979, to November 4, 1980; nor from December 12, 1980, to the date of the inspection. These periods exceed three months.

This is a Severity Level V violation (Supplement VII).

2. Condition No. 16 of your license requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in the referenced application and letter.

The referenced application dated August 14, 1979, states in Item 10 that the dose calibrator will be calibrated in accordance with Regulatory Guide 10.8, dated November 1977, Appendix D. Appendix D requires a linearity check to be performed quarterly.

Contrary to the above, as indicated by licensee representatives' statements, linearity checks have not been performed as required since the license was renewed on October 4, 1979.

This is a Severity Level V violation (Supplement VII).

3. Condition No. 16 of your license requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in the referenced application and letter.

The referenced letter dated September 5, 1979, states survey meters will be calibrated annually or after repair.


8106300543

Contrary to the above, a Picker CDV-700 survey meter used for area and package surveys was not calibrated from November 12, 1979, to March 18, 1981. This period exceeds one year.

This is a Severity Level V violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation. Consideration may be given to extending your response time for good cause shown.

Dated 6/18/81



D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2