



UNITED STATES  
 NUCLEAR REGULATORY COMMISSION  
 REGION V  
 1990 N. CALIFORNIA BOULEVARD  
 SUITE 202, WALNUT CREEK PLAZA  
 WALNUT CREEK, CALIFORNIA 94596

June 25, 1981

Docket No. 50-206

MATERIAL TRANSMITTED HEREWITH CONTAINS  
 2.790 INFORMATION



Southern California Edison Company  
 P. O. Box 800  
 2244 Walnut Grove Avenue  
 Rosemead, California 91770

Attention: Dr. L. T. Papay, Vice President  
 Advanced Engineering

Gentlemen:

This letter refers to the routine safeguards inspection of your activities authorized under NRC License No. DPR 13 conducted by Messrs. W. P. Mortensen, D. W. Schaefer and C. A. Schwan of this office on April 27 - May 1 and by W. P. Mortensen and C. A. Schwan on May 18-22, 1981. It also refers to the discussions of our inspection findings held by the inspectors with J. Dunn, J. Curran and members of their staff on May 1, May 22 and May 27, 1981.

The inspection included examination of activities related to your program for physical protection against radiological sabotage and against theft of special nuclear material in accordance with applicable requirements of Title 10, Code of Federal Regulations, Part 73, "Physical Protection of Plants and Materials", your Security Plan, and pertinent license conditions as described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and records, interviews with facility personnel and observations by the inspectors.

Within the scope of this inspection, four items of noncompliance were observed.

Based on the results of this inspection it appears that certain of your activities were not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. Pursuant to the provisions of 10 CFR 2.201 you are required to respond as indicated therein.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of findings of your security procedures are exempt from disclosure; therefore, the enclosures to this letter, the inspection report, and your response to the items listed in the enclosures to this letter will not be placed in the Public Document Room and will receive limited distribution.

MATERIAL TRANSMITTED HEREWITH CONTAINS  
 2.790 INFORMATION

IF02  
 5/11

8107010 106


Q

June 25, 1981

MATERIAL TRANSMITTED HEREWITH CONTAINS  
2790 INFORMATION

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,



G. S. Spencer, Director  
Divisi. of Technical Inspection

Enclosures:

- A. Appendix A - Notice of Violation
- B. Inspection Report No. 50-206/81-13  
(IE-V-440)

cc w/enclosures:

- R. Dietch, SCE
- J. M. Curran, SCE (San Clemente)

MATERIAL TRANSMITTED HEREWITH CONTAINS  
2790 INFORMATION