D

FORM NRC-591 (3-77)

ORIGINAL TO LICENSEE

U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

C	that Pillsfield	DPW	USURC	Megin I
60	o rivien si		Office & In	ejection and topocad
Pi	Hs field, MA	01201	631 PAN	PAUS IA PAIGYN
3. DO	CKET NUMBER(S)	4. LICENSE NUMBER	5)	B. DATE OF INSPECTION
3	0-09206	20-07,	113-05	Jane: 18, 1481
Comm	aspection was an examination of the act sission's rules and regulations and the co ive records, interviews with personnel, an	inditions of your license. The	inspection consisted of sel	radiation safety and to compliance with the ective examinations of procedures and repre of this inspection are as follows:
X	No items of noncompliance or uns	safe conditions were four	nd.	
The	following items of noncompliance re	elated to records, signs, a	nd labels were found:	
	A. Rooms or areas were not prope	rly posted to indicate the	e presence of a RADIAT	TION AREA. 10 CFR 20.203(b) or 34.4
	B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42			
	C. Rooms or areas were not properly possed to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)			
	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)			
	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)			
	F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)			
	G. FormNRC-3 was not properly	posted. 10 CFR 20.206(c	1) (31114)	27
	H. Records of the radiation exposure of individuals were not property maintained; 10 CFR 20401(a) or 34.33(b)			
	I. Records of surveys or disposals	were not properly maint	ained TO CFRED AD IN) or 34.43(d)
	J. Records of receipt, transfer, dis 10 CFR 30.51, 40.61 or 70.51	posal, export or inventor	U.S. HUCLEAR R	EGUATOKS [-0]
	K. Records of leak tests were not r	maintained as prescribed	in you heense, or 10 Cl	FR 34.25(g)
	L. Records of inventories were not	maintained. 10 CFR 34	26	TIET
	M. Utilization logs were not mainta	ained. 10 CFR 34.27	(<u>=</u>)	101
	N. Records of radiation survey inst	trument calibration were	not maintained. 10 CFF	R 34.24
	O. Records of teletherapy electrical interlock tests were not maintained as prescribed in your license.			
	P. Other		A THE REAL PROPERTY.	1
		Jes	my m	henor
	e NRC Inspector has explained a accompliance will be corrected with			The second secon
81 NM	07060146 810 618 S LIC30			
50	-07113-05 PDR			*
	(Date)		(Licensee Representati	e - Title or Position)