1. LIC	ENS		2. REGIONAL OFFICE	
0,4820	et de	Partment of the Army Ty Diamond faboratives Powder mill Road Iphi, HD 20783	U.S.Nuclear Regulatory Commission Office of Inspection & Enforcement Region I 631 Park Avenue King of Prussia, Pa. 19406	
19-	I P Sh	7250-01, -03, -04, -05 30-12438, 3 VM-348 30-12840,	70-00378 June 16,1981	
The in Comm	issic	CTION FINDINGS ection was an examination of the activities conducted under you	ur license as they relate to radiation safety and to compliance with the inspection consisted of selective examinations of procedures and repr	
1	N	to items of noncompliance or unsafe ditions were four	nd.	
The	foll	lowing items of noncompliance related to records, signs, a	and labels were found:	
			e presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.	
		Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42		
	C.	Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)		
	D.	Rooms or areas were not properly posted to indicate the	e presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e	
	E.	. Containers were not properly labeled to indicate the pre 10 CFR 20.203(f) (1) or (f) (2)	sence of RADIOACTIVE MATERIAL.	
	F.	A current copy of 10 CFR 20, a copy of the license, or a made available. 10 CFR 20.206(b)	a copy of the operating procedures was not properly posted of	
	G.	FormNRC-3 was not properly posted. 10 CFR 20.206(c)		
	H.	Records of the radiation exposure of individuals were no	ot properly maintained. 10 CFR 20 401(a) or 34.33(b)	
	1.	Records of surveys or disposals were not properly maint	ained. 10 CFR 20.401(b) or 34.43(d)	
	J.	Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51		
	Κ.	. Records of leak tests were not maintained as prescribed	in your license, or 10 CFR 34.25(c) 1197	
	L.	Records of inventories were not maintained. 10 CFR 34	26	
	Μ.	Utilization logs were not maintained. 10 CFR 34.27	S RELIVEN FA	
	N.	Records of radiation survey instrument calibration were	not maintained. 10 CFR24.24 111 0 2 1981	
	0.	Records of teletherapy electrical interlock tests were not	t maintained as prescribed in your license accuration	
	P.	Other	ja j	
		Lauren	e 7. Friedman, Pl. D., C.H.F.	
		RC Inspector has explained and I understand the ite mpliance will be corrected within the next 30 days.	The items of noncompliance listed above. The items of $I = \frac{1}{2} $	
		(Date)	(Licensee Representative - Title or Position)	