

APPENDIX A
NOTICE OF VIOLATION

Pharmatopes, Inc.
West Hartford, Connecticut 06002
License No. 06-19661-01MD

Docket No. 30-19066

As a result of the inspection conducted on June 1, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

Condition 23 of your license requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in your application dated January 8, 1981.


Item 21 of your application requires a high flow rate of air through your fume hood when xenon-133 is stored there.

Contrary to this requirement, on the day of the inspection, June 1, 1981, your fume hood in which millicurie quantities of xenon-133 were stored, failed to have a high flow rate of air since the exhaust fan was not turned on.

This is a Severity Level V Violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, Pharmatopes, Inc. is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

Dated 18 JUN 1981



John D. Kinneman, Chief
Materials Radiological Protection
Section