

DCD/DCB

DEC 15 1989

Rosemount  
KayRay/Sensall Division  
ATTN: Alan J. Peterson  
Radiation Safety Officer  
1400 Business Center Drive  
Mount Prospect, IL 60056

License No. 12-11184-01

30-04214

Gentlemen:

This refers to the special safety inspection conducted by Ms. C. C. Casey and Mr. B. A. Parker of this office during the period July 14 through November 16, 1989, of activities authorized by NRC Byproduct Material License No. 12-11184-01 and to the discussion of our findings with you in a telecon on November 15, 1989.

The inspection was conducted to review allegations concerning welder certifications for one of your vendors.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of interviews with personnel.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

No violations of NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Bruce S. Mallett, Ph.D., Chief  
Nuclear Materials Safety Branch

Enclosure: Inspection Report  
No. 030-04214/89001(DRSS)

cc w/enclosure:  
Linda Witonski, Danlin Corp.  
John DiMartino, Rosemount  
DCD/DCB (RIDS)

bbc w/enclosure:  
D. E. Funk

RIII  
Casey/jaw  
12/13/89

RIII  
Parker

RIII  
Sreniawski  
12/15/89

RIII  
Mallett  
12/15/89

IE 07