

YANKEE ATOMIC ELECTRIC COMPANY

Telephone (508) 779-6711
TWX 710-380-7619



580 Main Street, Bolton, Massachusetts 01740-1398

December 12, 1989

BYR 89-177

United States Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Reference: (a) License No. DPR-3 (Docket No. 50-29)

Subject: Special Report - Steam Generator Inspection Results from 1988
Refueling Outage


Dear Sirs:

The attached report submits the 1988 in-service inspection results for Steam Generator No. 3 at Yankee Nuclear Power Station. The inspection was performed in accordance with Technical Specification 4.4.10. This report satisfies the reporting requirements of Technical Specifications 4.4.10.5.b and 6.9.6.

We trust that you will find the attached report satisfactory; however, if you have any questions, please contact us.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY


George Papanic, Jr.
Senior Project Engineer
Licensing

GP/gjt/0673v

Attachment

cc: USNRC Region I
USNRC Resident Inspector, YNPS

9001030145 891212
PDR ADDCK 05600029
Q PNU

A047
11

MEMORANDUM

TO: G. Papanic _____ Date: December 7, 1989
FROM: K. J. Heider *Ken Heider* _____ File: RE 89-72
SUBJECT: Steam Generator Number 3 Inservice Inspection Report

This memorandum transmits a copy of the Steam Generator Number 3 inservice inspection report for the 1988 refueling outage. This report was compiled in compliance with Technical Specification 3.4.10. We understand that you will transmit a copy of the report to the NRC.

If you have any questions or require further information, please contact me at extension 303.

c: G. A. Maret (w/o attachment)
H. E. McKenney
R. A. Mellor