



SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30323

Report No.: 50-400/89-32

Licensee: Carolina Power and Light Company
P. O. Box 1551
Raleigh, NC 27602

Docket No.: 50-400

License No.: NPF-63,

Facility Name: Shearon Harris

Inspection Conducted: November 13-17, 1989

Inspectors:

W. J. Tobin
W. J. Tobin, Team Leader

12/15/89
Date Signed

A. Tillman
A. Tillman, Safeguards Inspector

12/18/89
Date Signed

O. Masnyk
O. Masnyk, Safeguards Inspector

12-15-89
Date Signed

W. Stansberry
W. Stansberry, Safeguards Inspector

12/18/89
Date Signed

Approved by:

D. R. McGuire
D. R. McGuire, Chief
Safeguards Section
Nuclear Materials Safety and Safeguards Branch
Division of Radiation Safety and Safeguards

12/18/89
Date Signed

SUMMARY

Scope:

This routine, unannounced inspection was conducted in the area of the Physical Security Program for Power Reactors, specifically, Management Support, Barriers, Detection, Access Controls, Alarm Stations, Power Supply, Training, Records and Contingency Response. Additionally, Generic Letter #89-07 and Inspector Followup Item #88-21-02 were reviewed, as were Safeguards Reports 89-S03, S04 and S05.

Results:

Two violations were identified.

- 89-32-01 Inadequate camera alarm assessment at the protected area barrier.
- 89-32-02 Inadequate personnel search.

9001030243 891218
PDR ADÖCK 05000400
Q PDC

SAFEGUARDS INFORMATION

Document transmitted herewith
contains sensitive unclassified
information. When separated from
enclosures, this document is decontrolled.

SAFEGUARDS INFORMATION

2

Generic Letter 89-07 and IFI 88-21-02 were "closed."

The inspectors commented favorably on the licensee's response to the Generic Letter.

SAFEGUARDS INFORMATION

Document transmitted herewith
contains sensitive unclassified
information. When separated from
enclosures, this document is decontrolled.