

APPENDIX A
NOTICE OF VIOLATION

State of Wyoming
Department of Environmental Quality
Bison Basin Mine

Docket No. 40-8926
License No. SUA-1492

During an inspection conducted on December 14, 1989, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1989)(Enforcement Policy), the violation is listed below:

License Condition No. 10 incorporates by reference, the August 3, 1989 Bison Basin Decommissioning submittal. This document requires, in part, that all liquid and solid material be disposed of at a designated disposal site.

Contrary to this, a portion of a plastic liner from a solution evaporation pond was diverted to a private residence in Riverton, Wyoming.


This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, the State of Wyoming, Department of Environmental Quality, is hereby required to submit to this office within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including for each violation:

1. the reason for the violation, if admitted;
2. the corrective steps which have been taken and the results achieved;
3. the corrective steps which will be taken to avoid further violations, and
4. the date when full compliance will be achieved.

When good cause is shown, consideration will be given to extending the response time.

Dated at NRC, Region IV, Uranium Recovery Field Office, this 19th day of December 1989.



Ramon E. Hall
Director
Uranium Recovery Field Office