SAFETY INSPECTION

DC D/DCB

1. LICENSEE

MCPHERSON COMMUNITY HEALTH CENTER 820 BYRON ROAD SUITE 300 HOWELL, MICHIGAN 48843

2. REGIONAL OFFICE

U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137

3. DOCKET NUMBER(S)

4. LICENSE NUMBER(S)

5. DATE OF INSPECTION

030-13402

21-17830-01

DECEMBER 21, 1989

L		

se as they relate to radiation safety and to compliance with the Nuclear
r license. The inspection consisted of selective examinations of procedures
nspector. The findings as a result of this inspection are as follows:
ons identified during the last inspection. We have no further questions on
n violation of NRC requirements.
coordance with 10 CFR 19.11.
was not properly posted to indicate the presence
was not properly posted to indicate the presence
were not properly
03(f)(1), or (f)(2).
of sealed sources were not performed at the proper
of sealed sources were not performed at the proper License Condition Number

D. Records of	were not properly maintained.	
10 CFR	or License Condition Number	
E. Documents were not properly posted or otherwise made available.	10 CFR 19.11.	
F. Reports or notifications of		were not made in accordance
with 10 CFR	or License Condition Number	
Пн		
		The state of the s

		
	-01221	
***************************************	2001120046 891221	
	2003 Lic30, PDC	
L_K	21-17830-01	

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC

SIGNATURE - LICENSEE