

JAN - 5 1990

In Reply Refer To:
License No.: 42-23539-01AF
USAF Permit Nos.: 21-10080-2AFP
21-21431-1AFP
21-30090-1AFP
21-30125-1AFP

Report No.: 89-07

Department of the Air Force
ATTN: Colonel David G. Wood
USAF Radioisotope Committee
HQ AFOMS/SGPR
Brooks AFB, Texas 78235-5000

Gentlemen:

This refers to the routine safety inspection conducted by Ms. E. R. Matson and Mr. W. T. King of the NRC Region III office on October 23, 1989, of activities authorized under USAF Permit Nos. 21-10080-2AFP, 21-30125-1AFP, 21-21431-1AFP, and 21-30090-1AFP issued to K. I. Sawyer AFB, Michigan, and to the discussion of our findings with Captain Gregory Zigulis at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter will be placed in the NRC Public Document Room.

Should you have any questions, please contact me at (817) 860-8215.

Sincerely,
Original Signed By:

William L. Fisher, Chief
Nuclear Materials Licensing Section

cc:
U.S. Nuclear Regulatory Commission
ATTN: Regional Administrator, Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

bcc: (see next page)

RIV:C:NMLS *WLF* MD:DESS
WLFisher/ch ABBeach
1/3/90 1/4/90

9001170351 900105
REG4 LIC30
42-23539-01AF FDC

IE 07

bcc:

DMB - Original (IE-07)

RDMartin

ABBeach

LAYandell

Glenda Jackson OC/LFMB (4503)

*CLCain

*WLFisher

*NMIS

*MIS System

*RIV Files (2)

*RSTS Operator

*REHall, URFO

*ERMatson, RIII

*WTKing, RIII

*BMallett, RIII

*W/766