Testmaster Inspection Company, Inc.

License No. 34-24871-01 FA 90-001

ATTN: W. B. Carr President

P. O. Box 31 Perrysburg, OH 43551

Gentlemen:

This refers to the special safety inspection conducted by Mr. W. Slawinski and Mr. W. Reichhold of this office on December 7 through 27, 1989, of activities authorized by NRC Byproduct Material License No. 34-24871-01 and to the discussion of our findings with you by telephone on January 3, 1990.

This special inspection was conducted in response to a report that a radiographer and his assistant may have received a whole body dose in excess of Part 20 limits. The enclosed copy of our inspection report identifies areas examined during the inspection. The inspection consisted of a selective review of procedures, records, a re-enactment of the incident, independent measurements, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements. You will be notified by separate correspondence of our decision regarding enforcement action based on the findings of this inspection. No written response is required until you are notified of the proposed enforcement action.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely.

DRIGINAL SIGNED BY C. E. NORELIUS

Charles E. Norelius, Director Division of Radiation Safety and Safequards

Enclosure: Inspection Report No. 030-29789/89001(DRSS)

bcc w/enclosure: J. Lieberman, OE

J. Goldberg, OGC

R. Bernero, NMSS

Reichhold/ib

9001260215 900116 REG3 LIC30 34-24871-01 PD PDC

RIII ESm Mallett History

1-12-90

RIII. Cuts/8m

(425) RIII Grobe Nore 1-12-20