JAN 04 1990

Docket No. 50-454 Docket No. 50-455

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

0

This refers to the routine safety inspection conducted by Mr. James Patterson and others of the NRC on December 5-8, 1989, of activities at the Byron Nuclear Power Station, Units 2 and 3, authorized by NRC Facility Operating Licenses No. NPF-37, and No. NPF-66, and to the discussion of our findings with Mr. Robert Ward and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Kege-

L. Robert Greger, Chief Reactor Programs Branch

Enclosure: Inspection Reports No. 50-454/89018(DRSS); No. 50-455/89020(DRSS)

stribution	Yes	yes	
RIII	RIII	RIII	RIIIfc
Foster	Barss		Clayton 1/3/90
	RIII Whs Foster	Yes	RIII RIII RIII Whs/n Pmb Whs Foster Barss Shell

PDC

9001300242 900104 PDR ADOCK 05000454

IF35

Greger

Ç.

37 19

-16

Commonwealth Edison Company

2 JAN 04 1990

Distribution cc w/enclosure: T. J. Maiman, Vice President, **PWR** Operations T. Kovach, Nuclear Licensing Manager R. Pleniewicz, Station Manager DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Byron Resident Inspector, RIII Braidwood D. W. Cassel, Jr., Esq. Richard Hubbard J. W. McCaffrey, Chief, Public Utilities Division Diane Chavez, DAARE/SAFE L. Olshan, NRR LPM H. S. Taylor, Quality Assurance Division D. Bement, FEMA, Region V R. Erickson, NRR, EPB