

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Reports No. 50-315/90002(DRSS); 50-316/90002(DRSS)

Docket Nos. 50-315; 50-316

Licenses No. DPR-58; DPR-74

Licensee: Indiana Michigan Power
Company
1 Riverside Plaza
Columbus, OH 43216

Facility Name: Donald C. Cook Nuclear Power Station, Units 1 and 2

Inspection At: Donald C. Cook Plant Site, Bridgman, Michigan

Inspection Conducted: January 8-12, 1990

Inspectors: Tony J. Madida for
James R. Kniceley
Physical Security Inspector

1/25/90
Date

Tony J. Madida for
Gary L. Pirtle
Physical Security Inspector

1/25/90
Date

Approved By: James R. Creed
James R. Creed, Chief
Safeguards Section

1/25/90
Date

Inspection Summary

Inspection on January 8-12, 1990 (Reports No. 50-315/90002(DRSS);
No. 50-316/90002(DRSS))

Areas Inspected: Routine, unannounced physical security inspection involving: Management Support and Effectiveness, Records and Reports, Compensatory Measures, Assessment Aids, Protected and Vital Area Barriers, Protected and Vital Area Detection Aids, Alarm Stations, Access Control Personnel, Testing and Maintenance, Security Training and Qualifications, TI 2515/102 "Land Vehicle Bomb Contingency Procedure Verification" (SIMS No. MPA L9-07) and review of previous inspection findings.

Results: The licensee was found to be in compliance with NRC requirements within the areas inspected. One previously identified item (50-315/88018-01 and 50-316/88201-01) was reviewed and closed. Temporary Instruction 2515/102 was reviewed and closed.

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Decontrolled

The licensee's performance meets regulatory requirements and the security program is adequately being implemented and managed.

(Details - Safeguards Information)

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Decontrolled