

DGD/RLB



JEWISH HOSPITAL
KENWOOD

January 22, 1990

Lin. no.
34-18868-01

Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Attn: A. Bert Davis, Regional Administrator


I am responding to your notification of a violation of 10 CFR Part 30.9(a), which was the result of an inspection conducted on July 7, 1988. This notification was received by Jewish Hospital Kenwood, formerly Otto C. Epp Memorial Hospital, on January 5, 1990.


As I reviewed the actions taken after the July 7, 1988 inspection, it is my belief that the problem has been corrected. We have switched to Dosimeter Corp. for service and calibration. They pick up the instrument and leave a report indicating date and description of work to be done. A sample is attached. Our staff checks this report for accuracy of dates when the instrument leaves the department and upon return. We believe this will leave a more verifiable paper trail than the one in place in 1988. We also have an additional survey instrument available to us to be used while our primary unit is being calibrated. This will allow total continuity in our survey process.

The Hospital Safety Officer is reviewing the recordkeeping on an ongoing basis for accuracy and completeness. Full compliance is effective at this time.

Sincerely yours,

License #34-18868-01
Docket #030-14283
EA #89-225


Betty J. Malloy
Vice President


E. P. Searfoss, D.O.
Radiation Safety Officer

cc: John H. Matthews, President/CEO
Greg Niemeyer, Hospital Safety Officer

attachment (1)

JAN 26 1990
IE07 1/0

9002130202 900122
REG3 LIC30
34-18868-01 FDC

