

APPENDIX B

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

NRC Inspection Report: 50-458/89-39 Operating License: NPF-47


Docket: 50-458


Licensee: Gulf States Utilities (GSU)
P.O. Box 220
St. Francisville, Louisiana 70775

Facility Name: River Bend Station (RBS)

Inspection At: RBS, St. Francisville, Louisiana

Inspection Conducted: November 13-17, 1989

Inspector:  2/1/90
A. B. Earnest, Physical Security Specialist Date
Security and Emergency Preparedness Section

Approved:  2/1/90
D. Powers, Chief, Security and Emergency Date
Preparedness Section

Inspection Summary

Inspection Conducted November 13-17, 1989 (Report 50-458/89-39)

Areas Inspected: Routine, unannounced inspection of the licensee's physical security program. The areas inspected within the physical security program included records and reports, management effectiveness, assessment aids, physical barriers - protected area (PA), detection aids - PA, compensatory measures, testing and maintenance, communications, and security system power supply.

Results: Within the program areas inspected, three apparent violations were identified (inadequate detection aids - PA, inadequate compensatory measures, and inadequate assessment aids). Two unresolved items (security system battery test and records and reports) are identified in paragraphs 3 and 11.

The licensee security management staff is relatively new to RBS. The staff is capable of resolving the issues identified in this report. The licensee's audit program should have identified some of the apparent violations discussed in this report, especially that compensatory procedure contradicts the Physical Security Plan (PSP) requirements.

**ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED**

9002140009 900207
PIR ADDCK 03000458
PDC
Q