JAN 2 5 1990

Maynard Steel Casting Company 2856 South 27th Street Milwaukee, WI 53215

Gentlemen:

As a result of the inspection conducted on December 20, 1989, a NRC Form 591, SAFETY INSPECTION, is issued for License No. 48-07080-01. The enclosed form sets forth the violation noted. Please acknowledge receipt of this form by signing and dating in the appropriate space on all copies. You are requested to retain the original and return four signed and dated copies to this office within ten days.

I wish to express my appreciation for the cooperation extended to me during the inspection.

Sincerely,

K. J. Lambert Radiation Specialist

Enclosure: NRC Form 591

cc w/enclosure: DCD/DCB (RIDS)

Ves RIII Lambert/rr



2E07

nco/aco

1. P.

6.3

l, i

LICENSEE		2. REGIONAL OFFICE	
MAYNARD STEEL CASTING COMPANY 2856 SOUTH 27TH STREET MILWAUKEE, WI 53215		U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137	
DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	B. DATE OF INSPECTION	
030-06743	48-07080-01	DECEMBER 20, 1989	
 In the scope of this inspection, it is inspection, it is inspection also verified the staps those actions at this time. In the scope of this inspection, it is is a notice of the staps of a	egulations and the conditions of your personnel, and observations by the in no violations were observed. you have taken to correct the violatio	was not properly posted to indicate the presen . 10 CFR 20.203(b), (c), (d), (e) or 34.4 . were not proper	
D. Records of 10 CFR	or or osted or otherwise made available. 10	License Condition Number	
X F. Reports or notifications of per with 10 CFR <u>20,407</u> H.		were not made in accordan	
K	ns described by me to the inspector w	III be taken to correct the violations identified in the items checked abov	
		of 10 CFR 2.201. No further response will be submitted unless required	

ŝ