GEGGEGENBUSTION ENGINEERING OWNERS GROUP

Arizone Public Service Co. Palo Verde 1, 2, 3 Arkenses Power & Light Co. ANO 2 Saltimore Gas & Electric Co. Calvert Cliffs 1, 2 Consumars Power Co. Palisades

Fluride Power & Light Co. 5: Lucie 1 2 Louislans Power & Light Co. Waterford 3 Maine Yankee Atomic Power Co. Mattic Yankee Northeast Utilities Service Co. Millistone 2 Omate Public Power District Ft Calhoun Southern California Edison Co. SONGS 2, 3

1/2/3

Edward C. Sterling, III, P.E., Chairman c/o Arizona Public Service/11226 N. 23rd Avenue Phoenix, AZ 85029/Station 7034

> January 18, 1990 CEOG-90-041

Mr. Frank J. Miraglia, Jr.
Associate Director for Inspection
and Technical Assessment
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Subject: Pressurizer Heater Sleeve Susceptibility to Primary Water Stress

Corrosion Cracking

Reference: CEOG-89-764 Dated November 17, 1989 - Same Subject

Dear Mr. Miraglia:

As requested by Mr. R. A. Hermann of your staff, the enclosed report, CEN-393-NP, "Evaluation of Pressurizer Heater Sleeve Susceptibility to Primary Water Stress Corrosion Cracking" is provided for your information.

This is a non-proprietary version of the report of same title as that provided via the referenced letter.

If you have any questions, please contact Joe Moaba (CEOG Inconel-600 Working Group Chairman) at (407) 694-4216 or me at (602) 340-4176.

Sincerely,

Edward C. Sterling

Chairman, C-E Owners Group

JWP/ECS/cmd

Enclosure: Report CEN-393-NP

cc Mr. R. A. Hermann (NRC)

9002260401 900118 PDR TOPRE EUTOSE 160/