

NOTICE OF VIOLATION

Northrup King Company

License No. 22-23522-01

As a result of the inspection conducted on January 25, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, (1989) (Enforcement Policy) the following violation was identified:

License Condition No. 16 requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in certain referenced documents.

The referenced January 16, 1987 application requires in Item No. 10 that laboratory radiation level and contamination survey results be converted to disintegrations per minute (dpm).

Contrary to the above, results of laboratory surveys performed in 1989 and 1990 were not converted to disintegrations per minute.

This is a Severity Level V violation (Supplement VI).
This is a repeat violation.

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) the corrective steps that have been taken and the results achieved; (2) the corrective steps that will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

February 15, 1990

R. J. Caniano
R. J. Caniano, Chief
Nuclear Materials Safety
Section 2

9002280031 900215
REG3 LIC80
22-23522-01 PDC