

NOTICE OF VIOLATION

Missouri Delta Community Hospital
Sikeston, Missouri

License No. 24-12876-01

As a result of the inspection conducted on January 17, 1990, and in accordance with 10 CFR Part 2, Appendix C - General Statement of Policy and Procedure for NRC Enforcement Actions (1989), the following violations were identified:

1. 10 CFR 35.634(a) requires that a licensee authorized to use teletherapy units for medical use perform output spot-checks on each teletherapy unit once in each calendar month.

Contrary to the above, from May 7, 1989 through August 22, 1989, the licensee failed to perform output spot-checks on their teletherapy unit.

This is a Severity Level IV violation (Supplement VI).

2. 10 CFR 35.615(d)(2) requires that a radiation monitor be equipped with a backup power supply separate from the power supply to the teletherapy room.

Contrary to the above, on the date of this inspection, the licensee's radiation monitor was not equipped with a separate backup power supply in that the backup batteries were nonfunctional.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

February 9, 1990
J

Roy J. Caniano
Roy J. Caniano, Chief
Nuclear Materials Safety
Section 2

9002280098 900209
REG3 LIC30
24-12876-01 FDC