FEB 0 9 1990

Syncor Corporation ATTN: Joe Huber

License No. 24-19360-01MD

Radiation Safety Officer

100 N. Euclid Avenue St. Louis, MO 63108

Gentlemen:

This refers to the routine safety inspection conducted by James R. Mullauer, M.H.S. of this office on January 25, 1990, of activities authorized by NRC Byproduct Material License No. 24-19360-01MD and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Roy J. Caniano, Chief Nuclear Materials Safety Section 2

cc: DCD/DCB (RIDS)

9002280104 900209 REG3 LIC30 24-29360-01MD PDC

Munlauer/mj

Cantago 190

IE07