U. S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

REGION I

So-245/80-09 So-336/80-06 DPR-21 Docket Nos. So-336 License Nos. DPR-65 Safeguards Group C
Licensee: Northeast Nuclear Energy Company
P. O. Box 270
Hartford, Connecticut 06101
Facility Name: Millstone Nuclear Power Station, Units 1 and 2
Inspection At:Waterford, Connecticut
Inspection Conducted: June 23-27,30 and July 1-3, 1980
Date of Last Physical Security Inspection: September 4-8, 1979
Type of Inspection: Routine, Unannounced Physical Protection Inspectors: R. Z. Shepherd R. E. Shepherd, Physical Security Inspector 1. M. McKeown, Physical Security Inspector Option 1770 1. M. McKeown, Physical Security Inspector Option 231783
Approved by: July 24,1980 J. W. Devlin, Chief, Security and Investigation date Scation, Safeguards Branch

Inspection Summary:

Inspection on June 23-27, 30 and July 1-3, 1980 (Combined Report Nos. 50-245/

80-09 and 50-336/80-06)

Areas Inspected: Included review of Security Plan; Security Program Audit; Security Organization; Physical Barriers (Protected Area and Vital Areas); Lighting; Access Controls (Identification, Authorization and Badging; Search; Escorting; Vital Areas); Alarm Stations; Detection Aids; Assessment Aids; Communications; Testing and Maintenance; Compensatory Measures; Power Supply; Response; Keys, Locks and Combinations; Records and Reports. Followup on IE Circular 80-09 regarding plant communications systems.

Region I Form 167 (August 1979) The inspection involved 120 inspector-hours onsite by two NRC inspectors. The inspection was begun during regular hours; 21 inspector-hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements within the 20 areas examined during this inspection except for the following 5 areas:

- 1. Physical Barriers (Vital Areas) two doors found unsecured (Infraction)
- Access Control (Authorization) two licensee vehicles found unlocked (Infraction)
- Access Control (Badging) required badge system not fully implemented (Infraction)
- Communications communications device did not function as required (Infraction)
- Testing and Maintenance special search device not tested as required (Infraction)