

TIC



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

JAN 30 1981

In Reply Refer To:

RII:JJL

50-321/80-51

50-366/80-51



Georgia Power Company
ATTN: J. H. Miller, Jr.
Executive Vice President
270 Peachtree Street
Atlanta, GA 30303

Gentlemen:

This refers to the meeting held at the NRC Region II Office on December 23, 1980 at our request. This meeting related to activities authorized by license numbers DPR-52 and NPF-5 and was attended by members of the Region II staff and Mr. T. Beckham and other members of your staff.

The subjects discussed at this meeting are included in the inspection report which is enclosed with this letter.

It is our opinion that this meeting was beneficial. It has provided a better understanding of the engineering evaluation and the schedule for completion of repairs to the backfill supporting the RHR and Service water pipes at the intake structure.

In accordance with Section 2.790 of NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulation, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room.

No reply to this letter is required; however, should you have any questions concerning this matter, we would be pleased to discuss them with you.

Sincerely,

Charles E. Murphy, Chief
Reactor Construction & Engineering
Support Branch

Enclosure: Inspection Report Nos.
50-321/80-51 and 50-366/80-51

cc: (See Page 2)

8108090 784

Georgia Power Company

-2-

JAN 20 1931

cc w/encl:

M. Manry, Plant Manager

C. E. Belflower, Site QA
Supervisor

W. A. Widner, Vice President
and General Manager