APPENDIX A

NOTICE OF VIOLATION

Pacific Gas and Electric Company Docket No. 50-133

Based on the results of an NRC inspection conducted on December 1-5, 1980, it appears that one of your activities was not conducted in full compliance with NRC regulations.

A. 10CFR71.5, "Transportation of licensed material," requires that no licensee deliver any licensed material to a carrier for transport, unless the licensee complies with the applicable requirements of the Department of Transportation regulations 49CFR170-189. 40CFR172.203(d) "Shipping Papers" requires that the description for a shi_dent of radioactive material must include the name of each radionuclide in the radioactive material that is listed in .9CFR173.390.

Contrary to the above, from August 3 to October 3, 1979, sixteen shipments of radioactive material identified as HB-CN-1 through HB-CN-16 contained transuranic radionuclides including: Americium 241, Curium 242, 243, 244, and Plutonium 238, 239, 240, that were not included in the description of the radioactive materials on the shipping papers. The specific activity of these transuranic radionuclides was calculated to be not greater than 13.3 nanocuries per gram.

This is an infraction.