



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

March 3, 1981

2R-0381-02

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Comm.
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



SUBJECT: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report No. 81-006/03L-0
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning the failure of the Containment Sump Level Indicator (2LI-5645-1).

Very truly yours,

David C. Trimble

David C. Trimble
Manager, Licensing

DCT:GAC:lp

Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Comm.
Washington, D.C. 20555

Mr. Norman M. Haller, Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Comm.
Washington, D.C. 20555

S 8103100507