

Appendix A

NOTICE OF VIOLATION

Shores Nuclear and Ultrasound Diagnostics

License No. 21-17223-01

As a result of the inspection conducted on May 12, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

10 CFR 35.14(e)(1)(i) states any licensee who possesses sealed sources as calibration or reference standards, which are greater than 100 microcuries, shall not use the sources in the absence of a certificate from the transferor indicating that a leak test has been made within six months prior to the transfer.


Contrary to the above, a 250 microcurie cesium-137 source and a 250 microcurie barium-133 source were placed into use on February 2, 1981, without the leak test certificates.

This is a Severity Level V violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within twenty-five days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

Date

5/29/81

  
D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2