

Docket No. 50-322

July 7, 1981

MEMORANDUM FOR: Harold R. Denton, Director, NRR
Darrell G. Eisenhut, Director, BOL
Richard H. Vollmer, Director, DOE
Roger J. Mattson, Director, DSI
Stephen H. Hanauer, Director, DHFS

FROM: Robert L. Tedesco, Assistant Director for
Licensing, DOL

SUBJECT: SHOREHAM SSER #1

Enclosed is Supplement #1 to the Shoreham Safety Evaluation Report. This report is presently being reviewed for typographical errors. Please provide your comments to Jerry Wilson by c.o.b. July 8, 1981. A careful review should be given to Section 1, 9.5, 13, I.C.6, I.D.1, II.B.7, II.K.1.23, and the attached memorandum from the resident inspector.

Robert L. Tedesco, Assistant Director
for Licensing
Division of Licensing

Enclosure:
As stated

DISTRIBUTION *up Encl.*
Docket File

LB #2

TERA

NSIC

TIC

RL Tedesco

ASchwencer

JWilson

L/PDR

NRC PDR



8107140196 810707
PDR ADOCK 05000322
E PDR

REGULATORY DOCKET FILE COPY

OFFICE	LB2	LB2	A/DL				
SURNAME	JWilson:sp	ASchwencer	RL Tedesco				
DATE	7/9/81	7/9/81	7/7/81				