Franklin Hospital ATTN: Mr. David Woodland 201 Bailey Lane Benton, IL 62812

License No. 12-04689-02

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. P. Reichhold of this office on June 26, 1:31, of activities authorized by NRC Byproduct Material License No. 12-04689-02 and to the telephone conversation concerning our findings with you on July 7, 1981.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in enclosed Appendix A. A written response, submitted under oath or affirmation, is required.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. G. Wiedeman, Acting Chief Materials Radiation Protection Section 1

Enclosure: Appendix A, Notice of Violation

cc w/encl: Elise Neeld, M.D. Pat Jones, R.T. DMB/Document Control Desk (RIDS)

RIII Reichhold/db 7/8/81 RIII Wiedeman REULIVEU

JUL 1 4 1981 - 10

U.S. MARGEAR SPOREATORS

U.S. MARGEAR SPOREATORS

TEOT

SIL

8107150170 810710 NMS LIC30 12-04689-02 PDR