



UNITED STATES
 NUCLEAR REGULATORY COMMISSION
 REGION V
 1990 N. CALIFORNIA BOULEVARD
 SUITE 202, WALNUT CREEK PLAZA
 WALNUT CREEK, CALIFORNIA 94596

June 24, 1981

License No. 53-11701-01

Wayne W. Wong M.D.
 615 Piikoi, Suite 510
 Honolulu, Hawaii 96814

Attention: Dr. Wayne W. Wong

Gentlemen:

Subject: NRC Inspection

This refers to the routine safety inspection conducted by Mr. Grayson of this office on May 12, 1981, of activities authorized by NRC License No. 53-11701-01 and to the discussion of our findings held by Mr. Grayson with you at the conclusion of the inspection.

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel and observations by the inspector.

During this inspection, it was found that one of your activities appeared to be in noncompliance with NRC requirements. This item and reference to the pertinent requirement are listed in Appendix A. This item has been categorized into a severity level as described in the Federal Register Notice (45 FR 6f754) dated October 7, 1980.

Your response to this notice is to be submitted in accordance with the provisions of 10 CFR 2.201 as stated in Appendix A, Notice of Violation.

If you have any questions on this matter or concerning this inspection, please telephone Mr. Grayson on 415-943-3700.

Sincerely,

H. E. Book

H. E. Book, Chief
 Radiological Safety Branch



Enclosure:
 A. Notice of Violation

*IEB
 5/11*