

APPENDIX A

NOTICE OF VIOLATION

Gamma Diagnostic Laboratories
Attleboro, Massachusetts 02763
License No. 20-15215-01MD

Docket No. 30-8748

Based on the results of an NRC inspection conducted on October 6 and 7, 1980, it appears that one of your activities was not conducted in full compliance with NRC regulations as indicated below:

10 CFR 20.207(a) requires that licensed materials, stored in an unrestricted area, be secured against unauthorized removal from the place of storage. 10 CFR 20.207(b) requires that materials not in storage be under constant surveillance and immediate control of the licensee. As defined in 10 CFR 20.3(a)(17), an unrestricted area is any area access to which is not controlled by the licensee for purposes of protection of individuals from exposure to radiation and radioactive materials.

Contrary to this requirement, on September 25, 1980, licensed materials were stored in your delivery vehicle which was in an unrestricted area and was neither under constant surveillance nor under your immediate control. We note that the materials were secured to the vehicle, but that the vehicle was unlocked and the engine running.

This is an infraction.

8107160510 810519
NMS LIC30
20-15215-01MD PDR