U.S. NUCLEAR REGULATORY COMMISSION

(3-77)

OFFICE OF INSPECTION AND ENFORCEMENT

LIC	ENSEE		2. REGIONAL OFFICE		
	U.S. Dept.of the Interior Bureau of Land Management 3040 Biddle Rd. Medford,Oregon, 97501		U.S. Nuclear Regulatory Commission 1990 N. California Blvd., Suite 202 Waln d t Creek, California 94596		
000	CKET NUMBER(S)	4. LICENSE NUMBER(S)	8	DATE OF INSPECTION	
		36-18337-01		5/8/81	
he in	PECTION FINDINGS inspection was an examination of the acti- tission's rules and regulations and the con- ive r cords, interviews with personnel, and	vities conducted under your ditions of your license. The it	aspection consisted of selection	iation safety and to compliance with the examinations of procedures and repr	
	No items of noncompliance or unsa	ife conditions were found			
The	following items of noncompliance re	lated to records, signs, and	d labels were found		
	A. Rooms or areas were not proper	ly posted to indicate the j	presence of a RADIATIO	N AREA. 10 CFR 20.203(b) or 34.	
	B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42				
0	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)				
	D. Rooms or areas were not proper	ly posted to indicate the	presence of RADIOACTI	VE MATERIAL. 10 CFR 20.203(c	
	E. Containers were not properly la 10 CFR 20.203(f) (1) or (f) (2)			1.00,	
	F. A current copy of 10 CFR 20, a made available. 10 CFR 20.2060	copy of the license, or a b)	copy of the operating pro	cerure REULOI VED Printy o	
51	G. FormNRC-3 was not properly p	osted, 10 CFR 20.206(c)		SI JUL 1 7 1981 - 21	
	H. Records of the radiation exposu			CER 20.4011 TOT 34 33(b)	
-					
		ecords of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34 43(d) ecords of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 0 CFR 30.51, 40.61 or 70.51			
-		naintained as prescribed it	vour license, or 10 CFR	34.25(c)	
	 K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c) L. Records of inventories were not maintained. 10 CFR 34.26 				
			20		
4	M. Utilization logs were not r inta			14.24 I E o l	
	N. Records of radiation survey inst				
	O. Records of teletherapy electrica	d interlock tests were not	maintained as prescribed	in your license.	
	P. Other	a biogeneration	an an an an the fer an alter of the state	and a star for the second s	
			NRC Aspecto	r)	
	he NRC Inspector has explained a oncompliance will be corrected wi	nd I understand the iter	ns of noncompliance li	sted above. The items of	
- 200	-3/15/51	Rould	Dandan	CHIEF CAR	
	107200313 810518		(Licenser Representative	Tisla Desitioni	