

JUL 17 1981



Paris Community Hospital
ATTN: Mr. William Vonderlage
Administrator
Post Office Box 299
Paris, Illinois 61944

License No. 12-14142-01

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. P. Reichhold of this office on June 22, 1981, of activities authorized by NRC Byproduct Material License No. 12-14142-01 and to the discussion of our findings with you and members of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

Our inspector expressed concern over an activity which appears to be in conflict with accepted radiological safety practices, as documented in Report 48 of the National Council on Radiation Protection, Section 4.2.F, page 20. Specifically, the molybdenum - technetium generator and generator storage areas are not locked when unattended. In your reply, please describe what actions you will take to ensure that these areas are locked when unattended.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in enclosed Appendix A. A written response, submitted under oath or affirmation, is required.

8107200365 810714
NMS LIC30
12-14142-01 PDR

TE07
5
111

JUL 14 1981

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

William J. Adon

for D. G. Wiedeman, Acting Chief
Materials Radiation Protection
Section 1

Enclosure: Appendix A,
Notice of Violation

cc w/encl:
Barry Sieff, M.D.
Gerald Brewington, R.T.
DMB/Document Control Desk (RIDS)

RIII

MR
Reichhold/so

7/7/81

RIII

WJ
Wiedeman