July 1, 1981

DONALSON X-RAY ASSOCIATES, P.C.

UNITED STATES NUCLEAR REGULATORY COMMISSION Region III 799 Roosevelt Road

BRINTON C DONALSON D.O.

609 E. JOHN RD.

LANERYS, MICHIGAN 48910

799 Roosevelt Road Glen Ellyn, Illinois 1010NE (517) 393-6150

Attention: Evelyn Matson

Re:

Brinton C. Donalson, D.O. License No. 21-15508-01

60137

609 E. Jolly Rd. Lansing, Mi. 48910

Dear Sirs:

This letter is a follow-up regarding the safety inspection by Ms. E. Matson, on February 24, 1981 and follow-up in the interim until todays phone call from Ms. Matson, to clear up the loose ends in the compliance apparatus.

In reference to my letter of May 22, 1981, items 1, 2 and 3 have been satisfactorily dealt with.

Item 4 refers to the G-M surveys and wipe tests conducted weekly. These will be personally reviewed with the technician monthly, on or about the first of the month, by myself.

Item 5 refers to the quarterly linearity test, which will be reviewed at the time of performance by mysolf, with the technician.

Item 6 refers to the data required on our exposure records and I am delighted to report that after a third letter to Landauer they are at last providing all the required information.

Since our last communication I have received a consultation from the University of Michigan Consulting Group, who have completed for me the plotting on graph paper of my linearity test so that I feel at this time I am in full compliance with the requirements previously described. This letter and the previous one of May 22, 1981 are submitted under affirmation to that affect.

Very Truly Yours,

Brinton C. Donalson, D.O.

Ticense No. 21-15508-01

8107200447 810701 NMS LIC30 21-15508-01 PDR

BCD/kb