FORM NRC-591 (3-77)

U.S. NUCLEAR REGULATORY COMMISSION

OFFICE OF INSPECTION AND ENFORCEMENT

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

| 1. LIC | ENSEE | | | 2. REGIONAL OF | 2. REGIONAL OFFICE | |
|--|--|---|----------------------------|--|--|--|
| Kallestad Laboratories, Inc. Research and Development Department Chaska, Minnesota 55318 | | | | U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137 | | |
| 3.00 | CKET NUMB | | 4. LICENSE NUM | | S. DAYE OF INSPECTION | |
| 03005055 03007639 03008006 | | 22-13838-01 | , 02E, 03G | July 8, 1981 | | |
| and the second second | PECTION FI | NDINGS | | | | |
| Comm | single or makes | s an examination of the a and regulations and the on interviews with personnel, a | conditions of your license | The increation consists. | ate to radiation holy and to tornaliance with the dof selective to principle of procedures and repre- | |
| X | No items | of noncompliance or u | nsafe conditions were | found. | ☐ JUL 20 1981 ► | |
| The | | tems of noncompliance | | | 12 | |
| | A. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42 | | | | | |
| | B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42 | | | | | |
| | C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d) | | | | | |
| | D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e) | | | | | |
| | E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2) | | | | | |
| | F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures vas not properly posted or made available. 10 CFR 20.206(b) | | | | | |
| | G. Form NRC-3 was not properly posted. 10 CFR 20.206(c) | | | | | |
| | H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b) | | | | | |
| | 1. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d) | | | | | |
| | J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51 | | | | | |
| | K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c) | | | | | |
| | L. Records of inventories were not maintained. 10 CFR 34.26 M. Utilization logs were not maintained. 10 CFR 34.27 | | | | IEOT | |
| | M. Utiliza | tion logs were not main | ntained. 10 CFR 34.2 | | , 1 | |
| | N. Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24 | | | | | |
| | O. Records of teletherapy electrical interlock tests were not maintained as prescribed in your license. | | | | | |
| | P. Other | | | | | |
| | | | | Donal R. | Lyban Inspector) | |
| | | spector has explained ce will be corrected | | | iance listed above. The items of | |
| - | | (Date) | | Usensee Ron | resentative - Title or Position) | |
| ORIGI | NAL TO LIC | | | темпесиер | The second secon | |

Most controlled Process