FORM NRC-591 (2-77)

U.S. NUCLEAR REGULATORY COMMISSION

OFFICE OF INSPECTION AND ENFORCEMENT

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

030-14733 24-18255			U.S. Nuclear Regulatory Commission Office Of Inspection and Enforcement Region III 799 Roosevelt RD. Glen Ellyn, IL. 60137	
		A. LICENSE NUMBER	*(5)	B. DATE OF INSPECTION
		24-18255-01		7/8/810110
The insponents	sion's rules and regulations and the records, interviews with personnel,	and observations by the insp	he inspection consisted of sector. The findings as a resu	a maritud
No items of noncompliance or unsafe conditions were four				JUL 20 1981 >
	ollowing items of noncompliance			CHAISSION
	A. Rooms or areas were not pro	operly posted to indicate t	he presence of a RADIA	ATION AREA JOCFR 20.203(b) of 34.4
	B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION ARÉALO 10 CFR 20.203(c) (1) or 34.42			
	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)			
	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e			
	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)			
	F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted of made available. 10 CFR 20.206(b)			
	G. FormNRC-3 was not properly posted. 10 CFR 20.206(c)			
	H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)			
X	I. Records of surveys continued were not properly maintained. 10 CFR 20.401(b) or 344(34)			
	J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51			
	K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)			
	L. Records of inventories were not maintained. 10 CFR 34.26			
	M. Utilization logs were not maintained. 10 CFR 34.27			
-	N. Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24			
	O. Records of teletherapy electrical interlock tests were not maintained as prescribed in your license.			
استعد	Other Quarterly line		rly accuracy che	cks of the dose calibrator
		Ant	(NRC Inspe	ector)
	NRC Inspector has explained ompliance will be corrected		tems of noncompliance	
/	18/8/	- landy	S. Work t	1. (Sypewar)
/	(Date)		(Licensee Representa	ative - Title or Position)

AND THE STREET STREET, STREET,

8107210256 810708 NMS LIC30 24-18255-01 PDR PDR