



United States Department of the Interior

7100

License No. 36-19313-01

BUREAU OF LAND MANAGEMENT

District Office

P.O. Box 550

Prineville, Oregon 97754

July 6, 1981

Nuclear Regulatory Commission, Region V
1990 N. California Blvd.
Suite 202, Walnut Creek Plaza
Walnut Creek, CA 95496



Attention: H. E. Book
Chief, Radiological Safety Branch

Subject: NRC Inspection Violation

Dear Mr. Book:

This refers to the routine safety inspection conducted by Mr. J. F. Pang of your office on May 21, 1981 of compliance with safety requirements under NRC License No. 36-19313-01. Pursuant to the provisions of 10 CFR 2.201, this letter is in reply to the notice of violations sent by NRC Radiological Safety Branch dated June 16, 1981.

A. 10 CFR 19.11(a) Severity Level VI Violations (Supplement VII)

A notice was posted on the outside of the storage cabinet to where documents: (1) 10 CFR 19 and 10 CFR 20; (2) the license, license conditions, or documents incorporated into a license by reference there to; and (3) the operating procedure applicable to licensed activities, may be examined at district office.

B. 10 CFR 20.401(a) Severity Level V Violations (Supplement VII)

The missing personnel monitoring records were obtained from the film badge processor (U.S Testing Co. Inc., Richland, Wash.) for the months of August, September, and October of 1980. This personnel monitoring records are now complete and on file at this office.

The district radiation protection officer shall maintain these records and equipment usage records to insure any new changes, deletions, or additions are carefully detailed to prevent further noncompliance to regulations.

Sincerely yours,

Paul W. Arrasmith
District Manager