

NORTHERN DIVISION CAMDEN, N.J. 08104 SOUTHERN DIVISION BERLIN, N.J. 08009 EASTERN DIVISION

VOORHEES, N.J. 08043

June 30, 1981

Docket No. 30-02442 License No. 29-01862-02

John D. Kinneman, Chief Materials Radiological Protection Section Technical Inspection Branch United States Nuclear Regulatory Commission Region 1 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Mr. Kinneman,

This in reply to the noncompliance for which we were cited during the combined inspection 7-70-2232/81-01 and 30-02443/81-01 on May 13, 1981.

Prior to January 1981, we have been following the procedures outlined in item 14 of our application in appendix F of the regulatory guide 10.8.

We had been erroneously informed by our consultant who stated that these measurements were not necessary to record unless they were elevated. Thus, we did not record the readings even though we did in fact monitor the packages of the radioactive material.

As of the 14th of May, 1981, we have been monitoring packages at three feet and at the surface. A wipe test of the surfaces is performed as well and the measurements are recorded.

Sincerely, Jose Department of Radiology Director, Nuclear Medicine

cc: Mr. Barry Brown JFC/SC

8107240135 810715 PDR ADOCK 07002232