

July 17, 1981

License No. 46-06377-04

U.S. Department of Commerce  
Northwest Fisheries Center  
2725 Montlake Boulevard, East  
Seattle, Washington 98102



Attention: Dr. William Roubal  
Radiation Safety Officer

Gentlemen:

Thank you for your letter dated June 29, 1981 informing us of the steps you have taken to correct items which we brought to your attention in our letter dated June 15, 1981. Your corrective actions will be verified during our next inspection.

You should be aware that License Condition 14 of your specific license requires that gas chromatograph detectors containing nickel-63 be tested for leakage and/or contamination only at intervals not to exceed six months, and that the results of those tests be maintained in units of microcuries.

Your cooperation with us is appreciated.

Sincerely,

Original signed by  
K. E. Book

H.E. Book, Chief  
Radiological Safety Branch

Sent to reproduction, HQ for distribution

Distributed by RV:  
State of Washington

IE07  
s  
1/1

8107240183 810717  
NMS LIC30  
46-06377-04 PDR

OFFICE	RV	RV	RV			
SURNAME	RIEDLINGER:frj	THOMAS	BOOK			
DATE	7/17/81	7/17/81	7/17/81			